

ELECTRICAL SAFETY RECALL

Clipsal 413-WE, PR413-WE and MP413-WE Surface Sockets



IDENTIFICATION:

Clipsal 413 product with datecode 201348 are potentially affected. Products were sold to and available for purchase from electrical wholesalers between dates of January 9, 2014 and February 21, 2014 (inclusive).

HAZARD:

Terminal colour identification has been reversed on some product. If the Active and Earth wires are terminated to match the colours on the affected units, there is a risk of electric shock if the surface socket is used with a Class 1 (earthed) appliance.

ACTION REQUIRED:

1. Check your current stock of this product.
2. Undertake a review of recent jobs done and assess all installations that might have used stock purchased or supplied in the relevant period, including risk assessments relating to installation and testing procedures, to determine whether physical inspection of product is necessary.
3. Where risks are identified, remain suspected or cannot be assessed, a physical inspection of product will be required in order to ensure removal of affected product.
4. Advise us the outcome of the inspection and return to us any defective product.

For further information

Please direct all calls and any queries concerning this recall to
Website: clipsal.com/413recall Phone: 1300 733 907

See www.recalls.gov.au for Australian product recall information